

PROJECT: WANDOO FLOW HOSE REPAIRS 2021 CLIENT: VERMILLION OIL & GAS

PROJECT DESCRIPTION

Vermilion Oil & Gas Australia (VOGA) engaged Oceanic Offshore Pty Ltd to undertake emergency Air Diving repair operations on the Wandoo CALM Buoy to replace the damaged floating hose assembly. The Wandoo field is located within Permit WA-14-L, located within the Commonwealth waters, which is approximately 75km North West offshore from Dampier Port, Western Australia.

THE CHALLENGE

Oceanic Offshore provided a suitable vessel and air diving services to assist VOGA with the removal of the damaged export Floating Hose Assembly (FHA) from the underside connection flange/spool piece located on the Wandoo field CALM Buoy. Once the old FHA was removed, the re-instatement of a new FHA to the CALM Buoy connection flange/spool piece was completed to allow the Field Service Vessel (FSV) to complete the construction of the flowline.

KEY OUTCOMES

The project was completed on time and on budget with zero safety incidents. Well Done to the Oceanic Offshore team!



